


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 31171	Main Street: POINTER_RD	Cross Street: BROWNE_RD	Location: SE
ADA ID: D90BE2AF02C0	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 26.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
 <p>Street 1 Name POINTER RD</p> <p>Stop Condition-Street 1 StopSign</p> <p>Street 2 Name N/A</p> <p>Stop Condition-Street 2 N/A</p>	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	68.0
			Yes	Ramp Width LT (in)	71.0
			Yes	Ramp Slope LT (%)	2.9
			No	Ramp XSlope LT (%)	2.3
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
			N/A	X Walk 1 Direction	To N
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	1.2
				X Walk 1 X Slope (%)	4.4
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	N/A
				Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	N/A
<p>Surveyor Notes:</p> <p>LT RP < 5%</p> <p>PROW/ADA:</p> <p>R304.5.3, R304.3.2</p> <p>Total Cost: \$ 1600.00</p>					

