


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 2853		Main Street: CARDINAL_POINT_RD		Cross Street: BENFIELD_RD		Location: SW																																																																																																																																																											
ADA ID: D91C66363EF2		Ramp Type: Directional1		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 7.5																																																																																																																																																									
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance																																																																																																																																																													
 Street 1 NameCARDINAL POINT RD Stop Condition-Street 1StopSign Street 2 NameN/A Stop Condition-Street 2N/A				Possible Solutions: Remove & Replace Entire Ramp. Remove & Replace Gutter. Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.2, R304.2.3, R304.5.3		<table><thead><tr><th>Compliance</th><th>Description</th><th>Data</th><th>Compliance</th><th>Description</th><th>Data</th></tr></thead><tbody><tr><td>N/A</td><td>Ramp Length (in)</td><td>77.0</td><td>No</td><td>Grade Break?</td><td>No</td></tr><tr><td>Yes</td><td>Ramp Width (in)</td><td>71.0</td><td>N/A</td><td>Grade Break Slope (%)</td><td>6.9</td></tr><tr><td>No</td><td>Ramp Slope (%)</td><td>8.4</td><td>N/A</td><td>Grade Break XSlope (%)</td><td>0.7</td></tr><tr><td>Yes</td><td>Ramp XSlope (%)</td><td>0.3</td><td></td><td></td><td></td></tr><tr><td>No</td><td>Flare Type LT</td><td>N/A</td><td>Yes</td><td>Flare Type RT</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Slope LT (%)</td><td>N/A</td><td>N/A</td><td>Flare Slope RT (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Traversable LT?</td><td>No</td><td>N/A</td><td>Flare Traversable RT?</td><td>No</td></tr><tr><td>Yes</td><td>Landing Length (in)</td><td>79.0</td><td>Yes</td><td>DWS Provided?</td><td>Yes</td></tr><tr><td>Yes</td><td>Landing Width (in)</td><td>70.0</td><td>Yes</td><td>DWS Contrast?</td><td>Yes</td></tr><tr><td>Yes</td><td>Landing Slope (%)</td><td>2.0</td><td>Yes</td><td>DWS Length (in)</td><td>24.0</td></tr><tr><td>Yes</td><td>Landing X Slope (%)</td><td>1.1</td><td>Yes</td><td>DWS Full Width?</td><td>Yes</td></tr><tr><td>N/A</td><td>Landing Curb? (Y/N)</td><td>N/A</td><td>Yes</td><td>DWS Offset LT (in)</td><td>0.5</td></tr><tr><td>N/A</td><td>Shared Landing?</td><td>Yes</td><td>Yes</td><td>DWS Offset RT (in)</td><td>60.0</td></tr><tr><td>Yes</td><td>Gutter Ponding?</td><td>No</td><td>Yes</td><td>Gutter Slope (%)</td><td>0.3</td></tr><tr><td>Yes</td><td>Gutter Lip Ht (in)</td><td>0.0</td><td>No</td><td>Gutter X Slope (%)</td><td>5.4</td></tr><tr><td>N/A</td><td>Painted X Walk1?</td><td>No</td><td></td><td>Road Slope (%)</td><td>4.5</td></tr><tr><td></td><td>X Walk 1 Direction</td><td>To N</td><td></td><td>Road X Slope (%)</td><td>6.5</td></tr><tr><td></td><td>X Walk 1 Width (in)</td><td>N/A</td><td></td><td>Clear Space?</td><td>Yes</td></tr><tr><td></td><td>X Walk 1 Slope (%)</td><td>4.5</td><td>N/A</td><td>Clear Space to XWalk (in)</td><td>N/A</td></tr><tr><td></td><td>X Walk 1 X Slope (%)</td><td>6.5</td><td>Yes</td><td>Storm Grate/Utility Hazard?</td><td>No</td></tr><tr><td>N/A</td><td>Ramp inside XWalk1?</td><td>N/A</td><td></td><td>Storm Grate/Utility Type</td><td></td></tr><tr><td>Yes</td><td>Any Obstructions?</td><td>No</td><td></td><td></td><td>N/A</td></tr><tr><td></td><td>Obstruction Type</td><td></td><td>Yes</td><td>Surface Condition? (G/P)</td><td>Good</td></tr><tr><td></td><td></td><td></td><td>N/A</td><td>Curb Slope (%)</td><td>7.2</td></tr></tbody></table>						Compliance	Description	Data	Compliance	Description	Data	N/A	Ramp Length (in)	77.0	No	Grade Break?	No	Yes	Ramp Width (in)	71.0	N/A	Grade Break Slope (%)	6.9	No	Ramp Slope (%)	8.4	N/A	Grade Break XSlope (%)	0.7	Yes	Ramp XSlope (%)	0.3				No	Flare Type LT	N/A	Yes	Flare Type RT	N/A	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	Yes	Landing Length (in)	79.0	Yes	DWS Provided?	Yes	Yes	Landing Width (in)	70.0	Yes	DWS Contrast?	Yes	Yes	Landing Slope (%)	2.0	Yes	DWS Length (in)	24.0	Yes	Landing X Slope (%)	1.1	Yes	DWS Full Width?	Yes	N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	0.5	N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	60.0	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.3	Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	5.4	N/A	Painted X Walk1?	No		Road Slope (%)	4.5		X Walk 1 Direction	To N		Road X Slope (%)	6.5		X Walk 1 Width (in)	N/A		Clear Space?	Yes		X Walk 1 Slope (%)	4.5	N/A	Clear Space to XWalk (in)	N/A		X Walk 1 X Slope (%)	6.5	Yes	Storm Grate/Utility Hazard?	No	N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		Yes	Any Obstructions?	No			N/A		Obstruction Type		Yes	Surface Condition? (G/P)	Good				N/A	Curb Slope (%)	7.2
Compliance	Description	Data	Compliance	Description	Data																																																																																																																																																												
N/A	Ramp Length (in)	77.0	No	Grade Break?	No																																																																																																																																																												
Yes	Ramp Width (in)	71.0	N/A	Grade Break Slope (%)	6.9																																																																																																																																																												
No	Ramp Slope (%)	8.4	N/A	Grade Break XSlope (%)	0.7																																																																																																																																																												
Yes	Ramp XSlope (%)	0.3																																																																																																																																																															
No	Flare Type LT	N/A	Yes	Flare Type RT	N/A																																																																																																																																																												
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A																																																																																																																																																												
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No																																																																																																																																																												
Yes	Landing Length (in)	79.0	Yes	DWS Provided?	Yes																																																																																																																																																												
Yes	Landing Width (in)	70.0	Yes	DWS Contrast?	Yes																																																																																																																																																												
Yes	Landing Slope (%)	2.0	Yes	DWS Length (in)	24.0																																																																																																																																																												
Yes	Landing X Slope (%)	1.1	Yes	DWS Full Width?	Yes																																																																																																																																																												
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	0.5																																																																																																																																																												
N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	60.0																																																																																																																																																												
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.3																																																																																																																																																												
Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	5.4																																																																																																																																																												
N/A	Painted X Walk1?	No		Road Slope (%)	4.5																																																																																																																																																												
	X Walk 1 Direction	To N		Road X Slope (%)	6.5																																																																																																																																																												
	X Walk 1 Width (in)	N/A		Clear Space?	Yes																																																																																																																																																												
	X Walk 1 Slope (%)	4.5	N/A	Clear Space to XWalk (in)	N/A																																																																																																																																																												
	X Walk 1 X Slope (%)	6.5	Yes	Storm Grate/Utility Hazard?	No																																																																																																																																																												
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type																																																																																																																																																													
Yes	Any Obstructions?	No			N/A																																																																																																																																																												
	Obstruction Type		Yes	Surface Condition? (G/P)	Good																																																																																																																																																												
			N/A	Curb Slope (%)	7.2																																																																																																																																																												
Total Cost:		\$		2350.00																																																																																																																																																													

