


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10020374		Main Street: BALLANTYNE CORPORATE PCross Street: N/A		Location: N															
ADA ID: D924A3600F56		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 1.25											
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance															
<div></div> <div>Street 1 NameENTRANCE</div> <div>Stop Condition-Street 1StopSign</div> <div>Street 2 NameN/A</div> <div>Stop Condition-Street 2N/A</div>				Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data			
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		77.0		N/A		Grade Break?		N/A		N/A	
						Yes		Ramp Width (in)		48.0		N/A		Grade Break Slope (%)		0.0		0.0	
						Yes		Ramp Slope (%)		2.2		N/A		Grade Break XSlope (%)		0.0		0.0	
						No		Ramp XSlope (%)		4.1									
						N/A		Flare Type LT		N/A		N/A		Flare Type RT		N/A		N/A	
						N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		0.0		0.0	
						N/A		Flare Traversable LT?		N/A		N/A		Flare Traversable RT?		N/A		N/A	
						N/A		Landing Length (in)		0.0		N/A		DWS Provided?		N/A		N/A	
						N/A		Landing Width (in)		0.0		N/A		DWS Contrast?		N/A		N/A	
						N/A		Landing Slope (%)		0.0		N/A		DWS Length (in)		N/A		N/A	
						N/A		Landing X Slope (%)		0.0		N/A		DWS Full Width?		N/A		N/A	
						N/A		Landing Curb? (Y/N)		N/A		N/A		DWS Offset LT (in)		N/A		N/A	
						N/A		Shared Landing?		N/A		N/A		DWS Offset RT (in)		N/A		N/A	
						N/A		Gutter Ponding?		0.0		N/A		Gutter Slope (%)		N/A		N/A	
						N/A		Gutter Lip Ht (in)		0.0		N/A		Gutter X Slope (%)		N/A		N/A	
						N/A		Painted X Walk1?		No				Road Slope (%)		1.8		1.8	
								X Walk 1 Direction		To SE				Road X Slope (%)		4.9		4.9	
								X Walk 1 Width (in)		N/A				Clear Space?		N/A		N/A	
								X Walk 1 Slope (%)		1.8		N/A		Clear Space to XWalk (in)		N/A		N/A	
				X Walk 1 X Slope (%)		4.9		N/A		Storm Grate/Utility Hazard?		N/A		N/A					
				N/A		Ramp inside XWalk1?		N/A		Storm Grate/Utility Type									
				N/A		Any Obstructions?		N/A						N/A					
						Obstruction Type				Yes		Surface Condition? (G/P)		Good					
								N/A		N/A		Curb Slope (%)		1.7					
				Total Cost:		\$		1600.00											

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

Total Cost:

\$ 1600.00

