

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 43409	Main Street: E_E_WADDELL_DR			Street:	NATIONS FORD RD	Location:	SW		
ADA ID: D95FC17AE5E7	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance			nce: N		12.5
· · · · ·					· · · · · · · · · · · · · · · · · · ·				
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
E E WADDELL DR		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Curb Ramp W	lith	N/A	Ramp Length (in)	103.0	Yes	Ramp Slope (%)	5.5
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
And and the		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	The second			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
Carl and the	A STATISTICS				X Walk 1 Direction	To E		X Walk 2 Direction	To N
and a strategy and a				N/A	X Walk 1 Width (in)	114.0	N/A	X Walk 2 Width (in)	97.0
Street 1 Name	NATIONS FORD RD				X Walk 1 Slope (%)	11.2		X Walk 2 Slope (%)	1.4
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	5.5
Street 2 Name	E E WADDELL DR			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	Signal				Road Slope (%)	4.0	N/A	Clear Space?	N/A
					Road X Slope (%)	5.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

