


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 13916	Main Street: CLANTON_RD	Cross Street: WEST_BV	Location: SW
ADA ID: D99D357A9D3E	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		No	Ramp Length (in)	60.0
	Restripe Crosswalk.		No	Ramp Width (in)	60.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
<p>Surveyor Notes:</p> <p>N/A</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
<p>PROW/ADA:</p> <p>Not Found, R304.2.2, R304.5.3</p>			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	Yes
				X Walk 1 Direction	To NE
			N/A	X Walk 1 Width (in)	104.0
				X Walk 1 Slope (%)	5.6
				X Walk 1 X Slope (%)	1.1
			N/A	Ramp inside XWalk1?	No
			N/A	Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
<p>Total Cost:</p> <p>\$ 2050.00</p>				Obstruction Type	
			N/A		
			N/A		
			N/A		
			N/A		
			N/A		
			N/A		
			N/A		
			N/A		
			N/A		
<p>Street 1 Name</p> <p>CLANTON RD</p>			Yes	Surface Condition? (G/P)	Good
<p>Stop Condition-Street 2</p> <p>Signal</p>					
<p>Street 2 Name</p> <p>N/A</p>					
<p>Stop Condition-Street 1</p> <p>N/A</p>					

