## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 10026307  | 07 Main Street: FAIRVIEW RD   |                               |   |  | N/A                   | Location: | NW                 |                             |      |
|--|---|-------------------------------|---|--|-----------------------|-----------|--------------------|-----------------------------|------|
| ADA ID: D99DF94D8E81   | Ramp Type: Perp   |                               |   | Initial Pass/Fail: Fail Overall Compliance: No |                       |           |                    |                             |      |
| Codes/Mitigation Info/Possible Solution  |   |                               | Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 26.25<br>Field Measurements/Component Compliance |  |                       |           |                    |                             |      |
|  |   | Possible Solutions:           |   |  |                       |           | liance Description | Data                        |      |
|  |   | Remove & Replace Entire Ramp. |   | N/A  | Ramp Length (in)      | 65.0      | No                 | Ramp Slope (%)              | 12.4 |
|  |   |                               |   | Yes  | Ramp Width (in)       | 48.0      | No                 | Ramp XSlope (%)             | 4.4  |
|  |   |                               |   | N/A  | Flare Type LT         | N/A       | N/A                | Flare Type RT               | N/A  |
| and the second s | U   |                               |   | N/A  | Flare Slope LT (%)    | N/A       | N/A                | Flare Slope RT (%)          | N/A  |
|  | A series of the |                               |   | N/A  | Flare Traversable LT? | N/A       | N/A                | Flare Traversable RT?       | N/A  |
| E State of the second se  |   |                               |   | N/A  | Landing Length (in)   | N/A       | N/A                | DWS Provided?               | N/A  |
|  |   | Surveyor Notes:               |   | N/A  | Landing Width (in)    | N/A       | N/A                | DWS Contrast?               | N/A  |
|  |   | N/A                           |   | N/A  | Landing Slope (%)     | N/A       | N/A                | DWS Length (in)             | N/A  |
| and the second s |   | 1071                          |   | N/A  | Landing X Slope (%)   | N/A       | N/A                | DWS Full Width?             | N/A  |
| FAIRVIEW RD  |   |                               |   | N/A  | Landing Curb? (Y/N)   | N/A       | N/A                | DWS Offset (in)             | N/A  |
|  | and the second  |                               |   | N/A  | Shared Landing?       | N/A       |                    | ζ, γ                        |      |
|  | 100 100 100 100 100 100 100 100 100 100   | PROW/ADA:                     |   | N/A  | Gutter Ponding?       | N/A       | N/A                | Gutter Slope (%)            | N/A  |
| the second second  | -   | R304.2.2, R304.5.3            |   | N/A  | Gutter Lip Ht (in)    | N/A       | N/A                | Gutter X Slope (%)          | N/A  |
|  | CONTRACTOR OF   |                               |   | N/A  | Painted X Walk1?      | No        | N/A                | Painted X Walk2?            | N/A  |
| and the second second second   | and the seal  |                               |   |  | X Walk 1 Direction    | To E      |                    | X Walk 2 Direction          | N/A  |
|  |   |                               |   | N/A  | X Walk 1 Width (in)   | N/A       | N/A                | X Walk 2 Width (in)         | N/A  |
| Street 1 Name  | ENTRANCE  | -                             |   |  | X Walk 1 Slope (%)    | 0.4       |                    | X Walk 2 Slope (%)          | N/A  |
| Stop Condition-Street 2  | StopSign  |                               |   |  | X Walk 1 X Slope (%)  | 4.1       |                    | X Walk 2 X Slope (%)        | N/A  |
| Street 2 Name  | N/A   |                               |   | N/A  | Ramp inside XWalk1?   | N/A       | N/A                | Ramp inside XWalk2?         | N/A  |
| Stop Condition-Street 1  | N/A   |                               |   |  | Road Slope (%)        | N/A       | N/A                | Clear Space?                | N/A  |
|  |   |                               |   |  | Road X Slope (%)      | N/A       | N/A                | Clear Space to XWalk (in)   | N/A  |
|  |   |                               |   | N/A  | Any Obstructions?     | N/A       | N/A                | Storm Grate/Utility Hazard? | N/A  |
|  |   | Total Cost: \$ 1              | 850.00  |  | Obstruction Type      |           |                    | Storm Grate/Utility Type    |      |
|  |   |                               |   |  |                       | N/A       |                    |                             | N/A  |

