

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

68.0

36.5

7.7

3.3

5.5

1.5

N/A

N/A

N/A N/A N/A

N/A

N/A N/A

N/A

N/A

No To W

N/A

2.2

0.2

N/A

N/A

N/A

Intersection ID: N/A Main Street: MUNSEE ST Cross Street: W SUGAR CREEK RD Location: SE Ramp Type: Combination2Diag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 0 **ADA ID: DA07EB40533C**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign **MUNSEE ST** None W SUGAR CREEK RD Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Sidewalk. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3

Total Cost:

Compliance Description		Data	Compl	iance	Description	
N/A	Ramp Length LT (in)	70.0	N/A	Ramp	Length RT (in)	
No	Ramp Width LT (in)	35.5	No	Ramp	Width RT (in)	
Yes	Ramp Slope LT (%)	3.2	Yes	Ramp	Slope RT (%)	
Yes	Ramp XSlope LT (%)	8.0	No	Ramp	XSlope RT (%)	
N/A	Ramp Length (in)	25.0	Yes	Ramp	Slope (%)	
Yes	Ramp Width (in)	48.0	Yes	Ramp	XSlope (%)	
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	
N/A	Landing Length (in)	N/A	N/A	DWS	DWS Provided?	
N/A	Landing Width (in)	N/A	N/A	DWS	DWS Contrast?	
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	
	X Walk 1 Width (in)	N/A		X Wa	lk 2 Width (in)	
	X Walk 1 Slope (%)	1.3		X Wa	lk 2 Slope (%)	

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

2.2

1.6

N/A N/A

2.5 N/A







N/A

3600.00

N/A	Any Obstruction?	N/A
	Obstruction Type	
		N/A
N/A	Storm Grate/Utility Hazard?	N/A
	Storm Grate/Utility Type	
		N/A
Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	19.4

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Clear Space?