

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14616	Main Street: BRIAR_CREEK_RD			Street:	E_INDEPENDENCE/BI	RA Location:	NW		
ADA ID: DA312AAE4C3C	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliand					10
			initiai						10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
- Contraction of the second	me la	Possible Solutions:		Compliance Description		Data Compliance Description			Data
	11/27	Remove & Replace Entire Ramp).	N/A	Ramp Length (in)	59.0	Yes	Ramp Slope (%)	5.2
	A she			No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.8
	How .			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	S. C.	1		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	WY.			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	All and	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
THE BRIAR OR EN INA		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
EINDEFENDENCE				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	SIS A V			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
E INDERENDENCEJERIAR ORIEK RA	Nº V			N/A	Shared Landing?	N/A			
CREEK RA		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
<u>b.</u>	112 1	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
DI DI				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
		1			X Walk 1 Direction	To S		X Walk 2 Direction	N/A
he dates and the	A REAL			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name E INDEPEN	IDENCE BV				X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

