

Access Compliance Report Public Rights-of-Way (Curb Ramps)



					-						
Intersection ID: 44786	Main Sti	Main Street: AYRSLEY_TOWN_BV				KINGS_PARADE_BV	Location:	NW			
ADA ID: DA4F6F026F06	Ramp T	Ramp Type: Perp			Pass/Fa	ail: Fail Overall C	o Severity Score:	10			
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
the state		Possible Solutions:		Compliance Description Dat			a Compliance Description		Data		
	× 9 1 /	Remove & Replace Ent	ire Ramr).	N/A	Ramp Length (in)	70.5	Yes	Ramp Slope (%)	6.2	
	7/19/ 201./			-	No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	4.8	
D THERE A	RUSLI				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	15 + x/.				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Land J	Statul d				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
Certin	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
ATTRELEY SE S S S N/A					N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
BV E					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
5	E E	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
R304.5.1, R304.5.3					N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
					N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
						X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	· · · ·				N/A	X Walk 1 Width (in)	114.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	AYRSLEY TOWN BV	-				X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

s Surface Condition? (G/P)

Good

