

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

14.8

Intersection ID: 13970 Main Street: STILWELL_OAKS_CR CI						Location:	SE			
					WILORA_LAKE_RD					
ADA ID: DA5FE355225A Ramp Type: Para			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
* ****		Possible Solutions:		Compliance Description Data			Compliance Description Data			
ALL F	1	Remove & Replace Entire Ram	р.	N/A	Ramp Length LT (in)	61.0	N/A	Ramp Length RT (in)	61.0	
	- 12			Yes	Ramp Width LT (in)	59.5	Yes	Ramp Width RT (in)	59.0	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				Yes	Ramp Slope LT (%)	6.3	No	Ramp Slope RT (%)	11.5	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Colles -	-		No	Ramp XSlope LT (%)	2.1	Yes	Ramp XSlope RT (%)	1.2	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
- AL	NG NO			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
VILLOW	A Start Start	Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
- L	et a start of the	N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
E C	Contraction of the second			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
g la				N/A	Shared Landing?	N/A				
	A CONTRACTOR			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	1 10-3-5 21	PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	The Al The of	R304.5.3, R304.3.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	Churcher S	· ·			X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
	A RECENTED			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	Statute				X Walk 1 Slope (%)	3.6		X Walk 2 Slope (%)	N/A	
Street 1 Name	STILLWELL OAKS CR				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A	
Stop Condition-Street 1	StopSign			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Street 2 Name	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
Stop Condition-Street 2	N/A				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
					Obstruction Type			Storm Grate/Utility Type		
		Total Cost: \$	1600.00			N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

