

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16187 Main Street: LANIER_AV Cross Street: LYNNVILLE_AV Location: SE

ADA ID: DA936A06A309 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
LYNNVILLE AV
Stop Condition-Street 1
StopSign
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:


N/A

PROW/ADA:

R304.5.3

No F
N/A F
N/A F
N/A L
N/A L
N/A L
N/A L
N/A C
N/A S
N/A F

Compliance Description Data		Compliance Description		Data	
N/A	Ramp Length (in)	37.0	N/A	N/A Grade Break?	
Yes	Ramp Width (in)	49.0	N/A	Grade Break Slope (%) 0.0
Yes	Ramp Slope (%)	4.9	N/A	Grade Break XSlope	(%) 0.0
No	Ramp XSlope (%)	10.9			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable R	r? N/A
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No		Road Slope (%)	0.0
	X Walk 1 Direction	To NE		Road X Slope (%)	1.7
	X Walk 1 Width (in)	N/A		Clear Space?	N/A
	X Walk 1 Slope (%)	0.0	N/A	Clear Space to XWa	lk (in) N/A
	X Walk 1 X Slope (%)	1.7	N/A	Storm Grate/Utility H	azard? N/A
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility T	уре
N/A	Any Obstructions?	N/A			N/A
	Obstruction Type		Yes	Surface Condition? (G/P) Good
		N/A	N/A	Curb Slope (%)	15.4





Total Cost:



1600.00