

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			_	/					
Intersection ID: N/A	Main Str	eet: CALDWELL_RD	Cross	Street:	CALDWELL_RIDGE_	PY		Location:	sw
ADA ID: DAD5AB1B10	B3 Ramp Ty	Ramp Type: Combination2Diag			Initial Pass/Fail: Fail Overall Compliance			o Severity Score:	0
	Codes/Mitigation Info							nent Compliance	
1 Contract		Possible Solutions:		Compliance Description			Data Compliance Description		
C. C.		Remove & Replace Curb Ram	p With	N/A	Ramp Length LT (in)	47.0	N/A	Ramp Length RT (in)	53.0
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0
				Yes	Ramp Slope LT (%)	5.4	Yes	Ramp Slope RT (%)	3.5
A A A A A A A A A A A A A A A A A A A				No	Ramp XSlope LT (%)	7.6	No	Ramp XSlope RT (%)	6.7
The sale of the				N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	3.2
	PRO MAN			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.7
A CONT	6.40	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	<u>e</u> 🕺 🔪 🛤	N/A		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	6.6.			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A ALT AL	N/B Carlo	1		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	A Reality	PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		Not Found, R304.5.3		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	and plan			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
5 A.S. ///	AND STATA			N/A	Shared Landing?	N/A			
and the first	ALERIA			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None	_		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	CALDWELL RD			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	StopSign				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
Stop Condition-Street 2	CALDWELL RIDGE PY				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	0.9
					X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	5.0
		Total Cost: \$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	3.7		Clear Space?	N/A
					Road X Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A
				100			N/A	Any Obstruction?	N/A
		-		Several and				Obstruction Type	
	2. 3 × 1 1 1 1		and the	and the second					

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

N/A

Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	41.3





