

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29416 Main Street: PADDERBORN CT **Cross Street: SALINGER WY** Location: N Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5 **ADA ID: DAE844C532F4** Ramp Type: Perp

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name PADDERBORN CT Stop Condition-Street 2 StopSign N/A Street 2 Name Stop Condition-Street 1 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: 1850.00

Compliance Description Data Compliance Description Data No N/A Ramp Length (in) 50.0 Ramp Slope (%) 9.8 47.5 No Ramp XSlope (%) No Ramp Width (in) 3.7 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To SE X Walk 2 Direction N/A N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) X Walk 2 Slope (%) N/A 2.4 X Walk 1 X Slope (%) 2.3 X Walk 2 X Slope (%) N/A N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? N/A Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





