


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 45490	Main Street: COTTON_STAND_RD	Cross Street: GRASSY_CROPS_RD	Location: SE
ADA ID: DBA8A0034F22	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	72.0	No
			No	Ramp Width (in)	37.0	Yes
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
			N/A	Painted X Walk1?	No	N/A
				X Walk 1 Direction	To N	To W
			N/A	X Walk 1 Width (in)	N/A	N/A
				X Walk 1 Slope (%)	2.9	X Walk 2 Slope (%)
				X Walk 1 X Slope (%)	4.7	X Walk 2 X Slope (%)
			N/A	Ramp inside XWalk1?	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p>				Road Slope (%)	1.3	N/A
				Road X Slope (%)	4.2	N/A
<p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.2.2</p>			N/A	Any Obstructions?	N/A	N/A
				Obstruction Type		
Total Cost:		\$ 3200.00				
					N/A	N/A
					Yes	Surface Condition? (G/P) Good

