

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 48393 Main Street: SHUFFLETOWN DR Cross Street: JOE MORRISON LN Location: S **Overall Compliance: No Severity Score:** 10 **ADA ID: DBDF55968A37** Ramp Type: PerpDiag Initial Pass/Fail: Fail

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance



SHUFFLETOWN DR Street 1 Name Stop Condition-Street 2 StopSign **JOE MORRISON LN** Street 2 Name Stop Condition-Street 1 None Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: R304.5.1, R304.5.3

Total Cost: 3200.00

Compliance Description Data Compliance Description Data Yes N/A Ramp Length (in) 74.0 Ramp Slope (%) 6.4 No Ramp XSlope (%) No Ramp Width (in) 44.0 4.0 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To NE X Walk 2 Direction To W N/A N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) 0.0 X Walk 2 Slope (%) 1.6 X Walk 1 X Slope (%) 4.6 X Walk 2 X Slope (%) 3.0 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 2.5 N/A Clear Space? N/A N/A Road X Slope (%) 1.0 Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





