

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			`		/						
Intersection ID: 7885	Main Street: MONTANA_DR				Cross Street: BEATTIES_FORD_RD				Location: SE		
ADA ID: DC29FF32E8BE	Ramp Type: Combination1			Initial	Initial Pass/Fail: Fail Overall Complian				nce: No Severity Score: 10		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	LARGE BURGER BURGER	Possible Solutions:			Compliance Description			Data Compliance Description			
		Remove & Replace	Entire Ram	מו.	N/A	Ramp Length LT (in)	41.0	N/A	Ramp Length RT (in)	46.0	
	ALL MERCENT			· P ·	Yes	Ramp Width LT (in)	72.0	Yes	Ramp Width RT (in)	71.5	
	The second second				Yes	Ramp Slope LT (%)	6.5	Yes	Ramp Slope RT (%)	3.0	
	the fit				No	Ramp XSlope LT (%)	2.8	No	Ramp XSlope RT (%)	2.6	
e e	The state				N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	7.9	
MONTANA DR	the second se				No	Ramp Width (in)	44.5	No	Ramp XSlope (%)	2.2	
	BERT_ST	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	at the at the	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
6. <u> </u>	PROPERTY OF				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	We all the				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	ALA STORAG				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		Not Found, R304.5.	1. R304.5.3	}	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
66 18	and the second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	Signal				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	MONTANA DR				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	120.5		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					4			N/A	Any Obstruction?	N/A	
									Obstruction Type		
The second se			Ster -	3 3 JA	A AL					N/A	
								N/A	Storm Grate/Utility Hazard?	N/A	

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 19.5





