

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/AMain Street:PINEVILLE-MATTHEWS\_RDCross Street: N/ALocation:SEADA ID: DC52BB961D92Ramp Type:PerpDiagInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

PINEVILLE-MATTHEWS RD
None
ENTRANCE

None

Possible Solution					
Possible Solutions:	<u>c</u>				
Remove & Replace Curb Ramp With					
Two New Directional Ramps or					
Equivalent.					
	N				
	N.				
	N				
Surveyor Notes:	N				
N/A	N				
	N				
	N				
	N.				
PROW/ADA:	N				
Not Found, R304.5.1	N.				
	N.				
	N				

Total Cost: \$ 3200.00

Fleid Measurements/Component Compilance								
	Compliance Description		Data	Compliance Description		Data		
	N/A	Ramp Length (in)	42.5	Yes	Ramp Slope (%)	6.7		
	No	Ramp Width (in)	44.0	Yes	Ramp XSlope (%)	2.3		
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
	N/A	Shared Landing?	N/A					
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No		
		X Walk 1 Direction	To N		X Walk 2 Direction	To W		
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
		X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	1.6		
		X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	3.1		
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
		Road Slope (%)	3.1	N/A	Clear Space?	N/A		
		Road X Slope (%)	0.3	N/A	Clear Space to XWalk (in)	N/A		
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
		Obstruction Type			Storm Grate/Utility Type			
			N/A			N/A		
				Yes	Surface Condition? (G/P)	Good		





