

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: N/A Main Street: MILLENNIUM\_AV Cross Street: POTOMAC\_RIVER\_PY Location: SE **Overall Compliance: No** ADA ID: DC7F465C5843 Ramp Type: Directional1 Initial Pass/Fail: Fail **Severity Score:** 1.25

**Codes/Mitigation Info/Possible Solution** 



| Street 1 Name           | POTOMAC RIVER PY |
|-------------------------|------------------|
| Stop Condition-Street 1 | StopSign         |
| Street 2 Name           | N/A              |
| Stop Condition-Street 2 | N/A              |

| Possible Solutions:           |
|-------------------------------|
| Remove & Replace Entire Ramp. |
|                               |
|                               |
|                               |
|                               |
| Surveyor Notes:               |
| N/A                           |
|                               |
|                               |
|                               |
| PROW/ADA:                     |
| R304.5.3                      |
|                               |
|                               |
|                               |
|                               |
|                               |
|                               |

| K304.3.3    |  |               |  |
|-------------|--|---------------|--|
| Total Cost: |  | \$<br>1600.00 |  |

| Field Measurements/Component Compliance |             |             |       |      |        |                         |      |  |  |
|---|-------------|-------------|-------|------|--------|-------------------------|------|--|--|
| Compli                                  | ance Des    | cription    | Data  | Comp | liance | Description             | Data |  |  |
| N/A                                     | Ramp Ler    | igth (in)   | 82.0  | N/A  | Grad   | e Break?                | N/A  |  |  |
| Yes                                     | Ramp Wid    | dth (in)    | 72.0  | N/A  | Grad   | 0.0                     |      |  |  |
| Yes                                     | Ramp Slo    | pe (%)      | 3.3   | N/A  | Grad   | 0.0                     |      |  |  |
| No                                      | Ramp XSI    | ope (%)     | 2.6   |      |        |                         |      |  |  |
| N/A                                     | Flare Type  | e LT        | N/A   | N/A  | Flare  | Type RT                 | N/A  |  |  |
| N/A                                     | Flare Slop  | e LT (%)    | N/A   | N/A  | Flare  | Slope RT (%)            | 0.0  |  |  |
| N/A                                     | Flare Trav  | ersable LT? | N/A   | N/A  | Flare  | Traversable RT?         | N/A  |  |  |
| N/A                                     | Landing L   | ength (in)  | 0.0   | N/A  | DWS    | Provided?               | N/A  |  |  |
| N/A                                     | Landing W   | /idth (in)  | 0.0   | N/A  | DWS    | Contrast?               | N/A  |  |  |
| N/A                                     | Landing S   | lope (%)    | 0.0   | N/A  | DWS    | Length (in)             | N/A  |  |  |
| N/A                                     | Landing X   | Slope (%)   | 0.0   | N/A  | DWS    | Full Width?             | N/A  |  |  |
| N/A                                     | Landing C   | urb? (Y/N)  | N/A   | N/A  | DWS    | Offset LT (in)          | N/A  |  |  |
| N/A                                     | Shared La   | inding?     | N/A   | N/A  | DWS    | Offset RT (in)          | N/A  |  |  |
| N/A                                     | Gutter Po   | nding?      | 0.0   | N/A  | Gutte  | er Slope (%)            | N/A  |  |  |
| N/A                                     | Gutter Lip  | Ht (in)     | 0.0   | N/A  | Gutte  | er X Slope (%)          | N/A  |  |  |
| N/A                                     | Painted X   | Walk1?      | Yes   |      | Road   | Slope (%)               | 4.7  |  |  |
|   | X Walk 1 [  | Direction   | To NW |      | Road   | I X Slope (%)           | 0.7  |  |  |
|   | X Walk 1 \  | Width (in)  | 72.0  |      | Clea   | r Space?                | N/A  |  |  |
|   | X Walk 1    | Slope (%)   | 4.7   | N/A  | Clea   | r Space to XWalk (in)   | N/A  |  |  |
|   | X Walk 1    | K Slope (%) | 0.7   | N/A  | Storr  | n Grate/Utility Hazard? | N/A  |  |  |
| N/A                                     | Ramp insi   | de XWalk1?  | Yes   |      | Storr  | n Grate/Utility Type    |      |  |  |
| N/A                                     | Any Obstr   | uctions?    | N/A   |      |        |                         | N/A  |  |  |
|   | Obstruction | n Type      |       | Yes  | Surfa  | ace Condition? (G/P)    | Good |  |  |
|   |             |             | N/A   | N/A  | Curb   | Slope (%)               | 1.5  |  |  |
|   |             |             |       |      |        |                         |      |  |  |





