## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11541 Main Street: W_9TH_ST				Stroot		Location:	W		
				Cross Street: N_PINE_ST					
ADA ID: DCA788E93BED	ID: DCA788E93BED Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description D			ata Compliance Description		Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	72.0	No	Ramp Slope (%)	9.2
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.2
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1 Martin			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	84. J. C. D.			N/A	Shared Landing?	N/A			
and the second s	A	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and a stand	19 6			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
and the second second				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE	
No mar and			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	N PINE ST	-			X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	10.2
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.3		X Walk 2 X Slope (%)	0.5
Street 2 Name	W 9TH ST			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	3.8	N/A	Clear Space?	N/A
					Road X Slope (%)	11.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P) Good

