

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14226 Main Street: AROSA AV **Cross Street: E MOREHEAD ST** Location: Ramp Type: PerpDiag **Overall Compliance: No** ADA ID: DCA7C9614571 Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 E MOREHEAD ST None AROSA AV StopSign

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

4.2.2, R304.5.3

	N/A
100	PROW/ADA: Not Found, R304
Т	
е	
V	
n	
	T

Total Cost: 3200.00

Comp	oliance	Description	Data	Comp	liance	Description	Data
N/A	Ramı	p Length (in)	80.0	No	Ramp	Slope (%)	10.2
Yes	Ramı	p Width (in)	48.0	No	Ram	XSlope (%)	2.9
N/A	Flare	Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare	Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare	Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Land	ing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Land	ing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Land	ing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Land	ing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Land	ing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Share	ed Landing?	N/A				
N/A	Gutte	er Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutte	er Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Paint	ed X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Wa	ılk 1 Direction	To NE		X Wa	lk 2 Direction	To NW
N/A	X Wa	ılk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Wa	ılk 1 Slope (%)	3.3		X Wa	lk 2 Slope (%)	6.4
	X Wa	ılk 1 X Slope (%)	1.1		X Wa	lk 2 X Slope (%)	1.8
N/A	Ram	p inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A
	Road	Slope (%)	3.5	N/A	Clear	Space?	N/A
	Road	I X Slope (%)	4.8	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any (Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obst	ruction Type			Storn	n Grate/Utility Type	
			N/A				N/A

Yes

Surface Condition? (G/P)

Good





