


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10035708	Main Street: REDDMAN_RD	Cross Street: N/A	Location: NE
ADA ID: DCB9D05B353C	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 12.5			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance			Description			Data	Compliance			Description			Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)		48.0		No	Ramp Slope (%)		10.1					
			Yes	Ramp Width (in)		48.0		Yes	Ramp XSlope (%)		0.1					
			N/A	Flare Type LT		N/A		N/A	Flare Type RT		N/A					
			N/A	Flare Slope LT (%)		N/A		N/A	Flare Slope RT (%)		N/A					
			N/A	Flare Traversable LT?		N/A		N/A	Flare Traversable RT?		N/A					
			N/A	Landing Length (in)		N/A		N/A	DWS Provided?		N/A					
			N/A	Landing Width (in)		N/A		N/A	DWS Contrast?		N/A					
			N/A	Landing Slope (%)		N/A		N/A	DWS Length (in)		N/A					
			N/A	Landing X Slope (%)		N/A		N/A	DWS Full Width?		N/A					
			N/A	Landing Curb? (Y/N)		N/A		N/A	DWS Offset (in)		N/A					
			N/A	Shared Landing?		N/A										
			N/A	Gutter Ponding?		N/A		N/A	Gutter Slope (%)		N/A					
			N/A	Gutter Lip Ht (in)		N/A		N/A	Gutter X Slope (%)		N/A					
			N/A	Painted X Walk1?		No		N/A	Painted X Walk2?		No					
				X Walk 1 Direction		To W			X Walk 2 Direction		To S					
			N/A	X Walk 1 Width (in)		N/A		N/A	X Walk 2 Width (in)		N/A					
				X Walk 1 Slope (%)		0.5			X Walk 2 Slope (%)		0.8					
				X Walk 1 X Slope (%)		0.8			X Walk 2 X Slope (%)		2.4					
		N/A	Ramp inside XWalk1?		N/A		N/A	Ramp inside XWalk2?		N/A						
			Road Slope (%)		0.3		N/A	Clear Space?		N/A						
			Road X Slope (%)		0.7		N/A	Clear Space to XWalk (in)		N/A						
		N/A	Any Obstructions?		N/A		N/A	Storm Grate/Utility Hazard?		N/A						
			Obstruction Type					Storm Grate/Utility Type								
							N/A			N/A						
							Yes	Surface Condition? (G/P)		Good						

