

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: STEELE_CREEK_RD Cross Street: N/A Location: NW **Overall Compliance: No** ADA ID: DCC8A3862C2E Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution



STEELE CREEK RD Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:							
Remove & Replace Entire Ramp.							
•							
Surveyor Notes:							
N/A							
PROW/ADA:							
Not Found, R304.2.2							
,							

Not Found, R304.2.2	
Total Cost:	\$ 1850.00

Field Measurements/Component Compliance									
Compli	ance Description	Data	Compli	ance	Description	Data			
N/A	Ramp Length (in)	60.0	No	Ramp	Slope (%)	8.6			
Yes	Ramp Width (in)	59.0	Yes	Ramp	XSlope (%)	0.9			
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	I/A Flare Slope RT (%)		N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?		N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?		N/A			
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A			
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	N/A			
	X Walk 1 Direction	To SE		X Wa	lk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	2.5		X Wa	lk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	8.0		X Wa	lk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm	Grate/Utility Type				
		N/A				N/A			
			Yes	Surfa	ce Condition? (G/P)	Good			





