

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

13.4

Intersection ID: 17464	64 Main Street: FALLS_CREEK_LN			Cross Street: SCALEYBARK_RD				Location:	W
ADA ID: DCE635F0B838	8 Ramp Type: ParaDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	La banena da	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.	mp With	N/A	Ramp Length LT (in)	56.0	N/A	Ramp Length RT (in)	60.0
			•	Yes	Ramp Width LT (in)	56.0	Yes	Ramp Width RT (in)	58.0
				Yes	Ramp Slope LT (%)	5.7	No	Ramp Slope RT (%)	9.5
· · ·				Yes	Ramp XSlope LT (%)	1.1	Yes	Ramp XSlope RT (%)	0.4
the state of a				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A REAL PROPERTY AND A REAL		Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
C. L. C. C.		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	0 5			N/A	Shared Landing?	N/A			
a line	the state			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
GILLER	the the second second	PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
ANDER		R304.3.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
and the second of a	the part of the second				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
					X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	4.7
Street 1 Name	FALLS CREEK LN				X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	0.8
Stop Condition-Street 1	None			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	SCALEYBARK RD				Road Slope (%)	2.0	N/A	Clear Space?	N/A
Stop Condition-Street 2	None				Road X Slope (%)	6.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	3200.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

