

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: N/A		Main Street: ANSLEY GARDEN DR	Cross Street: ZILKER PARK DR	Location:	E
ADA ID: DD30C56E928E		Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 0
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	87.0
			Yes	Ramp Width (in)	71.0
			Yes	Ramp Slope (%)	2.0
			Yes	Ramp XSlope (%)	1.2
			Yes	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	No
			Yes	Landing Length (in)	72.0
			Yes	Landing Width (in)	71.0
<p>Surveyor Notes:</p> <p>N/A</p>			No	Landing Slope (%)	2.5
			Yes	Landing X Slope (%)	1.9
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	Yes
			Yes	Gutter Ponding?	No
			Yes	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To NW
				X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	3.5
<p>PROW/ADA:</p> <p>Not Found, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305.2</p>			1.8	X Walk 1 X Slope (%)	Yes
			N/A	Ramp inside XWalk1?	N/A
			Yes	Any Obstructions?	No
				Obstruction Type	
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	21.7
Total Cost:		\$ 1600.00			

