


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10023411		Main Street: CHOATE_CR		Cross Street: N/A		Location:		SE											
ADA ID: DD547DC0D488		Ramp Type: Directional1		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 0											
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance															
<div></div> <div>Street 1 NameENTRANCE</div> <div>Stop Condition-Street 1None</div> <div>Street 2 NameN/A</div> <div>Stop Condition-Street 2N/A</div>				Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data			
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		81.0		Yes		Grade Break?		Yes			
				Remove & Replace Gutter.		Yes		Ramp Width (in)		72.0		Yes		Grade Break Slope (%)		0.3			
						Yes		Ramp Slope (%)		4.6		No		Grade Break XSlope (%)		2.3			
						Yes		Ramp XSlope (%)		1.5									
						Yes		Flare Type LT		N/A		Yes		Flare Type RT		N/A			
						N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		N/A			
				Surveyor Notes:		N/A		N/A		Flare Traversable LT?		No		N/A		Flare Traversable RT?		No	
								Yes		Landing Length (in)		60.0		Yes		DWS Provided?		Yes	
								Yes		Landing Width (in)		72.0		Yes		DWS Contrast?		Yes	
				Yes		Landing Slope (%)		1.9		Yes		DWS Length (in)		24.0					
				Yes		Landing X Slope (%)		1.2		Yes		DWS Full Width?		Yes					
PROW/ADA:		R304.5.3, R305.2		N/A		Landing Curb? (Y/N)		N/A		No		DWS Offset LT (in)		19.5					
				N/A		Shared Landing?		No		Yes		DWS Offset RT (in)		51.0					
				Yes		Gutter Ponding?		No		Yes		Gutter Slope (%)		0.9					
				Yes		Gutter Lip Ht (in)		0.0		No		Gutter X Slope (%)		2.8					
				N/A		Painted X Walk1?		No				Road Slope (%)		1.6					
						X Walk 1 Direction		To SW				Road X Slope (%)		1.3					
						X Walk 1 Width (in)		N/A				Clear Space?		Yes					
						X Walk 1 Slope (%)		1.6		N/A		Clear Space to XWalk (in)		N/A					
						X Walk 1 X Slope (%)		1.3		Yes		Storm Grate/Utility Hazard?		No					
				N/A		Ramp inside XWalk1?		N/A				Storm Grate/Utility Type							
				Yes		Any Obstructions?		No						N/A					
						Obstruction Type				Yes		Surface Condition? (G/P)		Good					
										N/A		Yes		Curb Slope (%)		5.9			
Total Cost:				\$		2350.00													