

Access Compliance Report Public Rights-of-Way (Curb Ramps)



l											
Intersection ID: 5210	52100 Main Street: FRED_D_ALEXANDER_BV				Street:	FREEDOM_DR	Location:	SE			
ADA ID: DD666A8D0I	F06 Ramp Ty	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
The second s		Possible Solutions:		Compliance Description			Data Compliance Description				
C. C. Martha Star	A A	Remove & Replace Entire	Ram	n	N/A	Ramp Length (in)	123.0	Yes	Ramp Slope (%)	5.7	
and the second second	AT A A A A A A A A A A A A A A A A A A		, itain	Ρ.	No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	3.2	
E.	(ASA)				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
6					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
6. 8 5					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	A A A A A A A A A	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
<u>6</u>	E. K	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	V. S. Sameral and				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	6. A CARACTER AND A C				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	PAGE TO PAGE				N/A	Shared Landing?	N/A				
B. B.	1 Martin	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	13	Not Found, R304.5.1, R30	04.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
					N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
Same S.F.						X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
	Cont. 1 2				N/A	X Walk 1 Width (in)	87.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	FRED D ALEXANDER BV					X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
4								1			

Yes Surface Condition? (G/P)

Good

