## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 22223	ersection ID: 22223 Main Street: HUCKLEBERRY_RD Cross Street: STOCKTIE_RD							Location:	N
ADA ID: DD680B972627	Ramp Type: PerpDiag		Initial P	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	35
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp W	'ith	N/A	Ramp Length (in)	70.0	No	Ramp Slope (%)	16.4
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.1
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	- Alte			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
STOR	S/ CAL			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
STILL ST	S/ a de de	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
K A		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1.			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Sec 2			N/A	Shared Landing?	N/A			
	West for the	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2,		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
R304.5.3				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	STOCKTIE RD				X Walk 1 Slope (%)	10.5		X Walk 2 Slope (%)	3.6
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	9.1
Street 2 Name H	UCKLEBERRY RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	10.3	N/A	Clear Space?	N/A
					Road X Slope (%)	4.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

