

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21661 Main Street: COLONY\_RD Cross Street: MONET\_TR Location: N

ADA ID: DD6EE7F6DB0E Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

COLONY RD None MONET TR StopSign Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

N/

Surveyor Notes:

N/A

N/

PROW/ADA:

R304.2.2, R304.5.3

Total Cost: \$ 3200.00

r leid Measurements/Component Comphance						
	Compliance Description		Data	Comp	liance Description	Data
	N/A	Ramp Length (in)	51.0	No	Ramp Slope (%)	10.7
	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.2
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	4.9
		X Walk 1 X Slope (%)	6.6		X Walk 2 X Slope (%)	1.9
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	6.0	N/A	Clear Space?	N/A
		Road X Slope (%)	5.0	N/A	Clear Space to XWalk (in)	N/A

N/A N/A

N/A

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

N/A

Good







N/A

Any Obstructions?

**Obstruction Type**