


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 23500	Main Street: OLD_PROVIDENCE_RD	Cross Street: REA_RD	Location: W
ADA ID: DD6F29C4EAB2	Ramp Type: ParaDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length LT (in)	46.0
			Yes	Ramp Width LT (in)	60.0
			Yes	Ramp Slope LT (%)	2.2
			No	Ramp XSlope LT (%)	2.1
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
<p>Surveyor Notes:</p> <p>LT RP < 5%</p> <p>PROW/ADA:</p> <p>R304.5.3, R304.3.2</p>			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To SE
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.0
				X Walk 1 X Slope (%)	4.3
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	1.8
<p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p> <p>REA RD</p> <p>None</p> <p>OLD PROVIDENCE RD</p> <p>StopSign</p>				Road X Slope (%)	3.5
			N/A	Any Obstructions?	N/A
				Obstruction Type	
<p>Total Cost:</p> <p>\$ 3200.00</p>			N/A		N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	33.2

