

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3381 Main Street: FAIRLEA\_DR Cross Street: WYNBOROUGH\_LN Location: NE
ADA ID: DD80109364EB Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

ADA ID: DD80109364EB Ramp Type: Directional1			Initial	Pass/Fa	ail: Fail Overall	Compliar	nce: N	o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
1		Possible Solutions:	Compliance Description			Data	Comp	oliance Description	Data
		Remove & Replace Entire Ram	p.	N/A	Ramp Length (in)	48.0	N/A	Grade Break?	N/A
WANTED TO STATE OF THE STATE OF				Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
				No	Ramp Slope (%)	11.1	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	2.9			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
<u>&amp;</u> \ 1	KENRLEA DR	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	RAINS			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No		Road Slope (%)	1.8
Street 1 Name	WYNBOROUGH LN				X Walk 1 Direction	To W		Road X Slope (%)	0.8
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	1.8	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.8	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	N/A





