

Access Compliance Report


Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11841	Main Street: E_18TH_ST	Cross Street: HARRILL_ST	Location:	N
ADA ID: DDBE35EFFE2D	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

RP SL < 5%

PROW/ADA:

Not Found, R304.5.3, R302.7

Total Cost: \$ 1600.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	74.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	57.5	No	Grade Break Slope (%)	5.5
Yes	Ramp Slope (%)	4.2	Yes	Grade Break XSlope (%)	0.9
Yes	Ramp XSlope (%)	0.6			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	58.5	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	58.5	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	0.9	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.2	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	20.0
N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	1.0
No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	1.7
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.9
N/A	Painted X Walk1?	No		Road Slope (%)	1.7
	X Walk 1 Direction	To SW		Road X Slope (%)	1.9
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	1.9	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	16.0

Street 1 Name	E 18TH ST
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

