

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19908Main Street:BROWN-GRIER_RDCross Street:GALLANT_LNLocation:NEADA ID: DDF9D62EDF36Ramp Type:Directional1Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



| THE RESERVE OF THE PARTY OF THE | |
|--|------------|
| Street 1 Name | GALLANT LN |
| Stop Condition-Street 1 | Signal |
| Street 2 Name | N/A |
| Stop Condition-Street 2 | N/A |

| <u>fo</u> | /Possible Solution | | Field Measurements/Component Compliance | | | | | |
|--------------------|-------------------------------|--------|---|-----------------------|-------|------|-----------------------------|------|
| THE REAL PROPERTY. | Possible Solutions: | | Comp | liance Description | Data | Comp | liance Description | Data |
| | Remove & Replace Entire Ramp. | | N/A | Ramp Length (in) | 90.0 | N/A | Grade Break? | N/A |
| | · | | Yes | Ramp Width (in) | 70.0 | N/A | Grade Break Slope (%) | 0.0 |
| | | | No | Ramp Slope (%) | 9.3 | N/A | Grade Break XSlope (%) | 0.0 |
| | | | Yes | Ramp XSlope (%) | 1.2 | | | |
| | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | 0.0 |
| | Surveyor Notes: | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | N/A | | N/A | Landing Length (in) | 0.0 | N/A | DWS Provided? | N/A |
| | | | N/A | Landing Width (in) | 0.0 | N/A | DWS Contrast? | N/A |
| | | | N/A | Landing Slope (%) | 0.0 | N/A | DWS Length (in) | N/A |
| 1 | | | N/A | Landing X Slope (%) | 0.0 | N/A | DWS Full Width? | N/A |
| pigi | PROW/ADA: | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset LT (in) | N/A |
| 25 | R304.2.2 | | N/A | Shared Landing? | N/A | N/A | DWS Offset RT (in) | N/A |
| | | | N/A | Gutter Ponding? | 0.0 | N/A | Gutter Slope (%) | N/A |
| | | | N/A | Gutter Lip Ht (in) | 0.0 | N/A | Gutter X Slope (%) | N/A |
| 4 | | | N/A | Painted X Walk1? | Yes | | Road Slope (%) | 2.3 |
| ı | | | | X Walk 1 Direction | To W | | Road X Slope (%) | 6.3 |
| I | | | | X Walk 1 Width (in) | 112.0 | | Clear Space? | N/A |
| | | | | X Walk 1 Slope (%) | 2.3 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | X Walk 1 X Slope (%) | 6.3 | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | N/A | Ramp inside XWalk1? | Yes | | Storm Grate/Utility Type | |
| | | | N/A | Any Obstructions? | N/A | | | N/A |
| | Total Cost: \$ 1 | 600.00 | | Obstruction Type | | Yes | Surface Condition? (G/P) | Good |
| | | | | | N/A | N/A | Curb Slope (%) | 7.8 |





