

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

65.0

49.0

6.4

8.0

1.8

3.1

N/A

No

To S

N/A

9.7

2.4

N/A

N/A

Intersection ID: 14033 Main Street: ELMIN ST **Cross Street: MORNING DR** NE Location: **Overall Compliance: No Severity Score:** 0 ADA ID: DE013890B5D8 Ramp Type: Combination2Diag Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Data

N/A

N/A

N/A

N/A

50.0

47.0

N/A

1.0

No

To W

N/A

4.5

9.7

N/A



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign **ELMIN ST**

None

WEST BV

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes: N/A

PROW/ADA:

R304.5.1, R304.5.3

Total Cost:

N/A N/A N/A N/A N/A N/A N/A 3200.00 N/A

X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%)

Compliance Description

N/A

N/A

N/A

N/A

N/A

No

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

3.1 13.8 N/A

Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 0.8 Curb Slope (%)





