


Intersection ID: N/A	Main Street: ARDREY_KELL_RD	Cross Street: WAVERLY_WALK_AV	Location:	SE
ADA ID: DE0E1B285027	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 12.5

Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.			N/A	Ramp Length (in)	96.0	N/A	Grade Break?	N/A
				Yes	Ramp Width (in)	89.0	N/A	Grade Break Slope (%)	0.0
				Yes	Ramp Slope (%)	3.8	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	5.9			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
Surveyor Notes:			N/A	N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
PROW/ADA:			R304.5.3	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
				N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes		Road Slope (%)	0.5
					X Walk 1 Direction	To W		Road X Slope (%)	1.3
					X Walk 1 Width (in)	113.0		Clear Space?	N/A
					X Walk 1 Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
					X Walk 1 X Slope (%)	1.3	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
					Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	1.5
Total Cost:			\$ 1600.00						
Street 1 Name				WAVERLY WALK AV					
Stop Condition-Street 1				StopSign					
Street 2 Name				N/A					
Stop Condition-Street 2				N/A					

