

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4167 Main Street: CLAUDE_FREEMAN_DR Cross Street: W_MALLARD_CREEK_CHURCH_RD Location: E

ADA ID: DE5532A51131 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Surface Condition? (G/P)

Good



Street 1 Name	MALLARD CREEK CHURCH RD
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

/Possible Solution		Field Measurements/Component Compliance							
Possible Solutions:		Comp	liance Description	Data	Comp	liance	Description	Data	
Remove & Replace Entire	Ramp.	N/A	Ramp Length (in)	74.5	Yes	Ramp	Slope (%)	5.3	
1	•	No	Ramp Width (in)	46.0	Yes	Ramp	XSlope (%)	2.0	
		N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A	
		N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A	
		N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A	
Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A	
N/A		N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A	
i		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A	
		N/A	Shared Landing?	N/A					
PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A	
R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A	
		N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	N/A	
			X Walk 1 Direction	To SW		X Wa	lk 2 Direction	N/A	
		N/A	X Walk 1 Width (in)	105.5	N/A	X Wa	lk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	0.9		X Wa	lk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	0.8		X Wa	lk 2 X Slope (%)	N/A	
		N/A	Ramp inside XWalk1?	Yes	N/A	Ramp	inside XWalk2?	N/A	
			Road Slope (%)	N/A	N/A	Clear	Space?	N/A	
			Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A	
Total Cost:	\$ 1850.00		Obstruction Type		l	Storm	n Grate/Utility Type		
				N/A				N/A	





