cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 27996 Main	Main Street: EDINDALE_DR		et: GOLS	PIE_CT	Location:	SE			
ADA ID: DEB4928957FE Ramp	Ramp Type: PerpDiag		nitial Pass/Fail: Fail Overall Compliance: I				o Severity Score:	37.5	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:	Co	Compliance Description D			ata Compliance Description		Data	
	Remove & Replace Curb Ramp W	ith N//	Ramp	Length (in)	92.0	No	Ramp Slope (%)	8.5	
	Two New Directional Ramps or	Ye		Width (in)	64.0	No	Ramp XSlope (%)	19.6	
	Equivalent.	N/A	Flare 1	Type LT	N/A	N/A	Flare Type RT	N/A	
		N//		Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N//	Flare T	raversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N//	Landin	g Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N//		g Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N//	Landin	g Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	1	N//		g X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N//		g Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N//		Landing?	N/A		ζ, γ		
	PROW/ADA:	N//	Gutter	Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.2.2, R304.5.3	N/#		Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N//		d X Walk1?	No	N/A	Painted X Walk2?	No	
the second se			X Walk	1 Direction	To N		X Walk 2 Direction	To W	
<u>a</u>		N//	X Walk	a 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name GOLSPIE C	 T			(1 Slope (%)	8.4		X Walk 2 Slope (%)	4.5	
Stop Condition-Street 2 StopSig	n			1 X Slope (%)	8.5		X Walk 2 X Slope (%)	12.7	
Street 2 Name EDINDALE D	R	N//		inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 Nor	e		Road S	Slope (%)	13.3	N/A	Clear Space?	N/A	
				K Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A	
		N//		ostructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	200.00		ction Type			Storm Grate/Utility Type		
					N/A			N/A	

