

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Intersection ID: 4059 Main Street: LAKEVIEW RD Cross Street: W W T HARRIS BV Location: NE **ADA ID: DECC08ABC5E2 Overall Compliance: No** Severity Score: 46.25 Ramp Type: Directional1 Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance Possible Solutions: Compliance Description Data Compliance Description Data N/A Grade Break? N/A Ramp Length (in) 42.5 N/A Remove & Replace Entire Ramp. 46.5 N/A No Ramp Width (in) Grade Break Slope (%) 0.0 N/A No Ramp Slope (%) 9.8 Grade Break XSlope (%) 0.0 Ramp XSlope (%) 7.9 No N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) 0.0 Surveyor Notes: N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A 0.0 N/A **DWS Provided?** N/A Landing Length (in) N/A **DWS Contrast?** N/A Landing Width (in) 0.0 N/A N/A N/A Landing Slope (%) 0.0 N/A DWS Length (in) N/A N/A N/A Landing X Slope (%) 0.0 DWS Full Width? N/A PROW/ADA: N/A Landing Curb? (Y/N) N/A N/A DWS Offset LT (in) N/A R304.5.1, R304.2.2, R304.5.3 N/A Shared Landing? N/A N/A DWS Offset RT (in) N/A N/A **Gutter Ponding?** 0.0 N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) 0.0 N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Road Slope (%) 0.5 W W T HARRIS BV To SW Street 1 Name X Walk 1 Direction Road X Slope (%) 1.6 Stop Condition-Street 1 Signal X Walk 1 Width (in) N/A Clear Space? N/A N/A X Walk 1 Slope (%) 0.5 N/A N/A Street 2 Name Clear Space to XWalk (in) Stop Condition-Street 2 N/A X Walk 1 X Slope (%) 1.6 N/A Storm Grate/Utility Hazard? N/A N/A Ramp inside XWalk1? N/A Storm Grate/Utility Type Any Obstructions? N/A N/A N/A Total Cost: **Obstruction Type** Surface Condition? (G/P) 1600.00 Yes Good N/A N/A Curb Slope (%)





