


Intersection ID: 10016063		Main Street: N TRYON ST		Cross Street: N/A		Location: NW													
ADA ID: DED305CAF575		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 1.25											
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance															
				Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data			
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		91.0		N/A		Grade Break?		N/A		0.0	
								Ramp Width (in)		98.0		N/A		Grade Break Slope (%)		0.0			
								Ramp Slope (%)		3.9		N/A		Grade Break XSlope (%)		0.0			
								Ramp XSlope (%)		2.2									
								Flare Type LT		N/A		N/A		Flare Type RT		N/A			
								Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		0.0			
								Flare Traversable LT?		N/A		N/A		Flare Traversable RT?		N/A			
								Landing Length (in)		0.0		N/A		DWS Provided?		N/A			
								Landing Width (in)		0.0		N/A		DWS Contrast?		N/A			
Surveyor Notes: N/A						N/A		0.0		N/A		DWS Length (in)		N/A					
						N/A		0.0		N/A		DWS Full Width?		N/A					
						N/A		0.0		N/A		DWS Offset LT (in)		N/A					
						N/A		0.0		N/A		DWS Offset RT (in)		N/A					
						N/A		0.0		N/A		Gutter Slope (%)		N/A					
						N/A		0.0		N/A		Gutter X Slope (%)		N/A					
						N/A		No				Road Slope (%)		1.8					
								X Walk 1 Direction		To S		Road X Slope (%)		0.4					
								X Walk 1 Width (in)		N/A		Clear Space?		N/A					
								X Walk 1 Slope (%)		1.8		N/A		Clear Space to XWalk (in)		N/A			
PROW/ADA: R304.5.3						0.4		N/A		Storm Grate/Utility Hazard?		N/A							
						N/A		N/A		Storm Grate/Utility Type									
						N/A		N/A											
						N/A		N/A											
						Obstruction Type		Yes		Surface Condition? (G/P)		Good							
								N/A		N/A		Curb Slope (%)		6.1					
Total Cost:				\$		1600.00													

