

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 53399 Main Street: COWGILL_LN **Cross Street: AGNEW_DR** Location: NW ADA ID: DED7C3D8B619 **Overall Compliance: No** Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution



Street 1 Name **COWGILL LN** StopSign Stop Condition-Street 2 Street 2 Name N/A N/A Stop Condition-Street 1

Possible Solutions:	Col
Remove & Replace Entire Ramp.	N/A
·	No
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.1	N/A
	N/A
	N/A
	N/A



Total Cost:



1850.00

Field Measurements/Component Compliance							
Compl	iance Description	Data	Comp	iance Description	Data		
N/A	Ramp Length (in)	99.0	Yes	Ramp Slope (%)	8.1		
No	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	1.1		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		