

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7015	Main Street: THE_ROMAN_RD			Street:	W_SUGAR_CREEK_R	Location:	NE		
ADA ID: DF1911FF9BA7 Ramp Type: Perp			initiai	Initial Pass/Fail: Fail Overall Compliance: No					8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	1	Possible Solutions:		Compliance Description Data			a Compliance Description		Data
		Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	61.0	Yes	Ramp Slope (%)	7.4
1 and the second	ANT ANT			No	Ramp Width (in)	44.0	Yes	Ramp XSlope (%)	1.3
	-	3		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		*		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A MARINE			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	and the second second	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	and an adde	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	AN RD			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	The new w			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	1 2 1			N/A	Shared Landing?	N/A			
A A A		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A .	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A
and a second sec	后			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name THI	E ROMAN RD				X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

