

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 17932	Main Street: SELWYN_AV	Cross Street: TRANQUIL_AV	Location: W
ADA ID: DF29B34B09BD	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 2.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.		Yes	Ramp Length (in)	96.0
			N/A	Ramp Width (in)	72.0
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	0.2
			N/A	Flare Traversable LT?	No
			Yes	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	2.8
			N/A	Flare Traversable RT?	No
			Yes	Landing Length (in)	48.0
Surveyor Notes: N/A			Yes	Landing Width (in)	72.0
			No	Landing Slope (%)	2.3
			Yes	Landing X Slope (%)	0.6
			N/A	Landing Curb? (Y/N)	No
			N/A	Landing Offset (in)	5.5
			N/A	Shared Landing?	No
			Yes	Gutter Ponding?	No
			Yes	Gutter Slope (%)	1.2
			No	Gutter X Slope (%)	2.5
			N/A	Gutter Lip Ht (in)	0.0
PROW/ADA: R304.5.3, R304.2.2-Perp, R304.3.2-Para, R305.1.4, R305.2			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To SE
			N/A	X Walk 2 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A
			N/A	X Walk 2 Width (in)	N/A
			6.3	X Walk 1 Slope (%)	2.6
			2.1	X Walk 1 X Slope (%)	0.7
			N/A	X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A
			N/A	Ramp inside XWalk2?	N/A
Total Cost: \$ 3950.00			0.8	Road Slope (%)	Yes
			5.3	Road X Slope (%)	N/A
			Yes	Clear Space?	Yes
			No	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No
				Storm Grate/Utility Hazard?	No
				Obstruction Type	
			N/A	Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

Street 1 Name **SELWYN AV**

Stop Condition-Street 2 **None**

Street 2 Name **TRANQUIL AV**

Stop Condition-Street 1 **StopSign**

