

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

60.0

60.0

13.1

2.4

5.2

4.4

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: N GRAHAM ST Location: Intersection ID: 9129 **Cross Street: NORRIS AV** SW Initial Pass/Fail: Fail **Overall Compliance: No** 35 **ADA ID: DF489FE82E61** Ramp Type: Combination1 **Severity Score:** 

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

Yes

No

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Flare Traversable RT?

Flare Type RT

Data

59.0

60.0

1.6 No

0.5

48.0

43.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name Signal Stop Condition-Street 1 **N GRAHAM ST** N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes Yes Yes N/A No Surveyor Notes: N/A LT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.5.3, N/A R304.3.2 N/A N/A N/A



Total Cost:



	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
		X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
		X Walk 1 Width (in)	117.5		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A
1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstruction?	N/A
- AND STATE OF THE PARTY OF THE					Obstruction Type	
	· ·					N/A
	1			N/A	Storm Grate/Utility Hazard?	N/A
				l	Storm Grate/Utility Type	
						N/A
	1			Yes	Surface Condition? (G/P)	Good
					Curb Slope (%)	24.7
A STATE OF THE PARTY OF THE PAR		A STATE OF THE PARTY OF THE PAR				

