## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 22616   | Itersection ID: 22616 Main Street: WOLFE_RIDGE_RD Cross Street: PARK_RD |                              |           |   |                       |      |      | Location:                   | SW    |
|--|---|------------------------------|-----------|---|-----------------------|------|------|-----------------------------|-------|
|  |   |                              |           |   |                       |      |      |                             |       |
| ADA ID: DF4AAAE3E685 Ramp Type: PerpDiag   |   |                              | Initial I | nitial Pass/Fail: Fail Overall Compliance: No |                       |      |      | b Severity Score:           | 26.25 |
| Codes/Mitigation Info/Possible Solution  |   |                              |           | Field Measurements/Component Compliance       |                       |      |      |                             |       |
| WOLFELRIDCELRD<br>C  |   | Possible Solutions:          |           | Compliance Description                        |                       |      | Comp | Data                        |       |
|  |   | Remove & Replace Curb Ramp W | Vith      | N/A   | Ramp Length (in)      | 57.0 | No   | Ramp Slope (%)              | 12.1  |
|  |   | Two New Directional Ramps or |           | Yes   | Ramp Width (in)       | 48.0 | No   | Ramp XSlope (%)             | 2.6   |
|  |   | Equivalent.                  |           | N/A   | Flare Type LT         | N/A  | N/A  | Flare Type RT               | N/A   |
|  |   |                              |           | N/A   | Flare Slope LT (%)    | N/A  | N/A  | Flare Slope RT (%)          | N/A   |
|  |   |                              |           | N/A   | Flare Traversable LT? | N/A  | N/A  | Flare Traversable RT?       | N/A   |
|  |   |                              |           | N/A   | Landing Length (in)   | N/A  | N/A  | DWS Provided?               | N/A   |
|  |   | Surveyor Notes:              |           | N/A   | Landing Width (in)    | N/A  | N/A  | DWS Contrast?               | N/A   |
|  |   | N/A                          |           | N/A   | Landing Slope (%)     | N/A  | N/A  | DWS Length (in)             | N/A   |
|  |   |                              |           | N/A   | Landing X Slope (%)   | N/A  | N/A  | DWS Full Width?             | N/A   |
|  |   |                              |           | N/A   | Landing Curb? (Y/N)   | N/A  | N/A  | DWS Offset (in)             | N/A   |
|  |   |                              |           | N/A   | Shared Landing?       | N/A  |      |                             |       |
|  |   | PROW/ADA:                    |           | N/A   | Gutter Ponding?       | N/A  | N/A  | Gutter Slope (%)            | N/A   |
| The second s |   | R304.2.2, R304.5.3           |           | N/A   | Gutter Lip Ht (in)    | N/A  | N/A  | Gutter X Slope (%)          | N/A   |
| Martin Carlos  |   | · ·                          |           | N/A   | Painted X Walk1?      | No   | N/A  | Painted X Walk2?            | No    |
|  |   |                              |           |   | X Walk 1 Direction    | To E |      | X Walk 2 Direction          | To N  |
|  |   |                              |           | N/A   | X Walk 1 Width (in)   | N/A  | N/A  | X Walk 2 Width (in)         | N/A   |
| Street 1 Name  | PARK RD   |                              |           |   | X Walk 1 Slope (%)    | 2.1  |      | X Walk 2 Slope (%)          | 1.1   |
| Stop Condition-Street 2  | None  |                              |           |   | X Walk 1 X Slope (%)  | 0.2  |      | X Walk 2 X Slope (%)        | 0.3   |
| Street 2 Name  | WOLFE RIDGE RD  |                              |           | N/A   | Ramp inside XWalk1?   | N/A  | N/A  | Ramp inside XWalk2?         | N/A   |
| Stop Condition-Street 1  | StopSign  |                              |           |   | Road Slope (%)        | 0.1  | N/A  | Clear Space?                | N/A   |
|  |   |                              |           |   | Road X Slope (%)      | 1.6  | N/A  | Clear Space to XWalk (in)   | N/A   |
|  |   |                              |           | N/A   | Any Obstructions?     | N/A  | N/A  | Storm Grate/Utility Hazard? | N/A   |
|  |   | Total Cost: \$ 3             | 200.00    |   | Obstruction Type      |      |      | Storm Grate/Utility Type    |       |
|  |   |                              |           |   |                       | N/A  |      |                             | N/A   |

Yes Surface Condition? (G/P)

Good

