

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			•	. ,						
Intersection ID: 52314	Main Str	Cross Street: IMPATIEN_DR				Location:		NW		
ADA ID: DF8044277D99	Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Complian				nce: No Severity Score: 21.2	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description		Data Compliance Description		bliance Description	Data	
	4 1 1 6 6 6 2	Remove & Replace E	ntire Ramp.	N/	A	Ramp Length LT (in)	35.0	N/A	Ramp Length RT (in)	35.0
				Ye	s	Ramp Width LT (in)	71.5	Yes	Ramp Width RT (in)	74.0
				Ye	s	Ramp Slope LT (%)	5.4	Yes	Ramp Slope RT (%)	6.3
the state of the state of the				Ye	s	Ramp XSlope LT (%)	0.3	Yes	Ramp XSlope RT (%)	0.4
				N/	Ά	Ramp Length (in)	80.0	Yes	Ramp Slope (%)	2.2
				No	b	Ramp Width (in)	47.0	No	Ramp XSlope (%)	6.4
		Surveyor Notes:		N/	Α	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		CURB GAP 1.0		N/	Α	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
MPAULEN S.				N/	Ά	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E ANA DR				N/	Α	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Comments of the second s	Y			N/	Α	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second	1	PROW/ADA:		N/	Α	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
L.	Prod 2	Not Found, R304.5.1	, R304.5.3	N/	Α	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	A SAR A		,	N/	Α	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	10 10 1 1 a 10			N/	Α	Shared Landing?	N/A			
C. C. 10 17 1 18	1 Person			N/	Α	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None			N/.	Α	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	JOHN RUSSELL RD			N/	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	7.1		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$ 18	00.00 N/	Ά	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
								N/A	Any Obstruction?	N/A
	A BANK					~			Obstruction Type	
The second se	Chan Day					and the second				N/A
			ST-					Ν/Δ	Storm Grate/Litility Hazard?	

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good

14.3

Curb Slope (%)



