


Intersection ID: 52449	Main Street: TRANQUIL_OAK_PL	Cross Street: PAT_GARRETT_ST	Location:	SW
ADA ID: E021E21AD9A8	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 26.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance																																																																													
<div></div> <div>Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2</div> <div>TRANQUIL OAK PL StopSign N/A N/A</div>			Possible Solutions:			<table><tr><th>Compliance</th><th>Description</th><th>Data</th></tr><tr><td>N/A</td><td>Ramp Length (in)</td><td>66.0</td></tr><tr><td>Yes</td><td>Ramp Width (in)</td><td>66.0</td></tr><tr><td>No</td><td>Ramp Slope (%)</td><td>15.6</td></tr><tr><td>No</td><td>Ramp XSlope (%)</td><td>3.0</td></tr><tr><td>N/A</td><td>Flare Type LT</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Slope LT (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Traversable LT?</td><td>N/A</td></tr><tr><td>N/A</td><td>Landing Length (in)</td><td>0.0</td></tr><tr><td>N/A</td><td>Landing Width (in)</td><td>0.0</td></tr><tr><td>N/A</td><td>Landing Slope (%)</td><td>0.0</td></tr><tr><td>N/A</td><td>Landing X Slope (%)</td><td>0.0</td></tr><tr><td>N/A</td><td>Landing Curb? (Y/N)</td><td>N/A</td></tr><tr><td>N/A</td><td>Shared Landing?</td><td>N/A</td></tr><tr><td>N/A</td><td>Gutter Ponding?</td><td>0.0</td></tr><tr><td>N/A</td><td>Gutter Lip Ht (in)</td><td>1.0</td></tr><tr><td>N/A</td><td>Painted X Walk1?</td><td>No</td></tr><tr><td></td><td>X Walk 1 Direction</td><td>To E</td></tr><tr><td></td><td>X Walk 1 Width (in)</td><td>N/A</td></tr><tr><td></td><td>X Walk 1 Slope (%)</td><td>2.4</td></tr><tr><td></td><td>X Walk 1 X Slope (%)</td><td>1.8</td></tr><tr><td>N/A</td><td>Ramp inside XWalk1?</td><td>N/A</td></tr><tr><td>N/A</td><td>Any Obstructions?</td><td>N/A</td></tr><tr><td></td><td>Obstruction Type</td><td></td></tr></table>			Compliance	Description	Data	N/A	Ramp Length (in)	66.0	Yes	Ramp Width (in)	66.0	No	Ramp Slope (%)	15.6	No	Ramp XSlope (%)	3.0	N/A	Flare Type LT	N/A	N/A	Flare Slope LT (%)	N/A	N/A	Flare Traversable LT?	N/A	N/A	Landing Length (in)	0.0	N/A	Landing Width (in)	0.0	N/A	Landing Slope (%)	0.0	N/A	Landing X Slope (%)	0.0	N/A	Landing Curb? (Y/N)	N/A	N/A	Shared Landing?	N/A	N/A	Gutter Ponding?	0.0	N/A	Gutter Lip Ht (in)	1.0	N/A	Painted X Walk1?	No		X Walk 1 Direction	To E		X Walk 1 Width (in)	N/A		X Walk 1 Slope (%)	2.4		X Walk 1 X Slope (%)	1.8	N/A	Ramp inside XWalk1?	N/A	N/A	Any Obstructions?	N/A		Obstruction Type	
			Compliance	Description	Data																																																																											
N/A	Ramp Length (in)	66.0																																																																														
Yes	Ramp Width (in)	66.0																																																																														
No	Ramp Slope (%)	15.6																																																																														
No	Ramp XSlope (%)	3.0																																																																														
N/A	Flare Type LT	N/A																																																																														
N/A	Flare Slope LT (%)	N/A																																																																														
N/A	Flare Traversable LT?	N/A																																																																														
N/A	Landing Length (in)	0.0																																																																														
N/A	Landing Width (in)	0.0																																																																														
N/A	Landing Slope (%)	0.0																																																																														
N/A	Landing X Slope (%)	0.0																																																																														
N/A	Landing Curb? (Y/N)	N/A																																																																														
N/A	Shared Landing?	N/A																																																																														
N/A	Gutter Ponding?	0.0																																																																														
N/A	Gutter Lip Ht (in)	1.0																																																																														
N/A	Painted X Walk1?	No																																																																														
	X Walk 1 Direction	To E																																																																														
	X Walk 1 Width (in)	N/A																																																																														
	X Walk 1 Slope (%)	2.4																																																																														
	X Walk 1 X Slope (%)	1.8																																																																														
N/A	Ramp inside XWalk1?	N/A																																																																														
N/A	Any Obstructions?	N/A																																																																														
	Obstruction Type																																																																															
Remove & Replace Entire Ramp.			<table><tr><th>Compliance</th><th>Description</th><th>Data</th></tr><tr><td>N/A</td><td>Grade Break?</td><td>N/A</td></tr><tr><td>N/A</td><td>Grade Break Slope (%)</td><td>0.0</td></tr><tr><td>N/A</td><td>Grade Break XSlope (%)</td><td>0.0</td></tr><tr><td>N/A</td><td>Flare Type RT</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Slope RT (%)</td><td>0.0</td></tr><tr><td>N/A</td><td>Flare Traversable RT?</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Provided?</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Contrast?</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Length (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Full Width?</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Offset LT (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>DWS Offset RT (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>Gutter Slope (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Gutter X Slope (%)</td><td>N/A</td></tr><tr><td></td><td>Road Slope (%)</td><td>2.4</td></tr><tr><td></td><td>Road X Slope (%)</td><td>1.8</td></tr><tr><td></td><td>Clear Space?</td><td>N/A</td></tr><tr><td>N/A</td><td>Clear Space to XWalk (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>Storm Grate/Utility Hazard?</td><td>N/A</td></tr><tr><td></td><td>Storm Grate/Utility Type</td><td></td></tr><tr><td></td><td>Surface Condition? (G/P)</td><td>Good</td></tr><tr><td></td><td>Curb Slope (%)</td><td>10.5</td></tr></table>			Compliance	Description	Data	N/A	Grade Break?	N/A	N/A	Grade Break Slope (%)	0.0	N/A	Grade Break XSlope (%)	0.0	N/A	Flare Type RT	N/A	N/A	Flare Slope RT (%)	0.0	N/A	Flare Traversable RT?	N/A	N/A	DWS Provided?	N/A	N/A	DWS Contrast?	N/A	N/A	DWS Length (in)	N/A	N/A	DWS Full Width?	N/A	N/A	DWS Offset LT (in)	N/A	N/A	DWS Offset RT (in)	N/A	N/A	Gutter Slope (%)	N/A	N/A	Gutter X Slope (%)	N/A		Road Slope (%)	2.4		Road X Slope (%)	1.8		Clear Space?	N/A	N/A	Clear Space to XWalk (in)	N/A	N/A	Storm Grate/Utility Hazard?	N/A		Storm Grate/Utility Type			Surface Condition? (G/P)	Good		Curb Slope (%)	10.5						
Compliance	Description	Data																																																																														
N/A	Grade Break?	N/A																																																																														
N/A	Grade Break Slope (%)	0.0																																																																														
N/A	Grade Break XSlope (%)	0.0																																																																														
N/A	Flare Type RT	N/A																																																																														
N/A	Flare Slope RT (%)	0.0																																																																														
N/A	Flare Traversable RT?	N/A																																																																														
N/A	DWS Provided?	N/A																																																																														
N/A	DWS Contrast?	N/A																																																																														
N/A	DWS Length (in)	N/A																																																																														
N/A	DWS Full Width?	N/A																																																																														
N/A	DWS Offset LT (in)	N/A																																																																														
N/A	DWS Offset RT (in)	N/A																																																																														
N/A	Gutter Slope (%)	N/A																																																																														
N/A	Gutter X Slope (%)	N/A																																																																														
	Road Slope (%)	2.4																																																																														
	Road X Slope (%)	1.8																																																																														
	Clear Space?	N/A																																																																														
N/A	Clear Space to XWalk (in)	N/A																																																																														
N/A	Storm Grate/Utility Hazard?	N/A																																																																														
	Storm Grate/Utility Type																																																																															
	Surface Condition? (G/P)	Good																																																																														
	Curb Slope (%)	10.5																																																																														
Surveyor Notes:																																																																																
N/A																																																																																
PROW/ADA:																																																																																
R304.2.2, R304.5.3																																																																																
Total Cost:			\$ 1600.00																																																																													

