cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Curb Slope (%)

Good

19.9

			`		,						
Intersection ID: 16319	Main Street: SLOAN_ST				Cross Street: TYSON_ST				Location: E		
ADA ID: E0757BD7D627	Ramp Type: Combination2			Initial Pass/Fail: Fail Overall Com			Complian	npliance: No Severity Score:		25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description		Data		liance Description	Data		
	L Y	Remove & Replace	Entire Ramp.	1	I/A	Ramp Length LT (in)	N/A	N/A	Ramp Length RT (in)	57.0	
		•	•	1	A/A	Ramp Width LT (in)	N/A	Yes	Ramp Width RT (in)	55.0	
	11.			1	A/A	Ramp Slope LT (%)	N/A	No	Ramp Slope RT (%)	10.9	
	1			1	A/A	Ramp XSlope LT (%)	N/A	No	Ramp XSlope RT (%)	2.8	
				1	N/A	Ramp Length (in)	25.0	No	Ramp Slope (%)	10.0	
and the second second				١	/es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	6.2	
6 97		Surveyor Notes:		1	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the second se	A	N/A		1	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
K A				1	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	All have			1	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	ALC: NO			1	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	By Mar	PROW/ADA:		1	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
No. 1	No. We	Not Found, R304.2.2	2, R304.5.3,	1	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
he has	X497 1 4	R304.3.2		1	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				1	N/A	Shared Landing?	N/A				
				1	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None			N	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	SLOAN ST			1	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	5.0		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$ 16	00.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
	And The state		10110 01	-	A			N/A	Any Obstruction?	N/A	
					North State	and the second second			Obstruction Type		
	-			E						N/A	
				C. The				N/A	Storm Grate/Utility Hazard?	N/A	
			5	and the state of t					Storm Grate/Utility Type	17/4	
		17-1	A.S.			Contraction of the second				N/A	
			and the second	and the second s	NAME OF CASE	and the second se				<u> </u>	