## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46369	Main Street: DIXIE_HILLS_DR			Cross Street: ROYAL_CASTLE_CT				Location:	NW
ADA ID: E08697EE1426	6 Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	o With	N/A	Ramp Length (in)	44.0	No	Ramp Slope (%)	11.4
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.3
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	E			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Citized South		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	i and	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A G				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
and the second	100	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.2.2, R304.5.3				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ROYAL CASTLE CT				X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	6.7
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	1.5
Street 2 Name	DIXIE HILLS DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	1.1	N/A	Clear Space?	N/A
					Road X Slope (%)	5.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		·				N/A			N/A
							1		

**Yes** Surface Condition? (G/P)

Good

