

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

0.0

0.0

N/A

0.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

3.0

2.8

N/A

N/A

N/A

N/A

Good

12.3

Intersection ID: 10037314 Main Street: SARDIS_RD Cross Street: N/A Location: NE

ADA ID: E0B43D4B9F70 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Compliance Description

Ramp Length (in)

Ramp Width (in)

N/A

Yes

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

N/A

Compliance Description

Grade Break?

Grade Break Slope (%)

Data

66.0

70.0



Street 1 Name ENTRANCE
Stop Condition-Street 1 StopSign
Street 2 Name N/A
Stop Condition-Street 2 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.2.2

N/A No Ramp Slope (%) 11.5 Grade Break XSlope (%) Ramp XSlope (%) 0.5 Yes N/A Flare Type LT N/A N/A Flare Type RT N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A 0.0 N/A **DWS Provided?** Landing Length (in) N/A **DWS Contrast?** N/A Landing Width (in) 0.0 N/A Landing Slope (%) 0.0 N/A DWS Length (in) N/A 0.0 N/A DWS Full Width? Landing X Slope (%) N/A Landing Curb? (Y/N) N/A N/A DWS Offset LT (in) N/A Shared Landing? N/A N/A DWS Offset RT (in) N/A **Gutter Ponding?** 0.0 N/A Gutter Slope (%) N/A Gutter Lip Ht (in) 0.0 N/A Gutter X Slope (%) N/A Painted X Walk1? No Road Slope (%) To S X Walk 1 Direction Road X Slope (%) X Walk 1 Width (in) N/A Clear Space? X Walk 1 Slope (%) 3.0 N/A Clear Space to XWalk (in) X Walk 1 X Slope (%) 2.8 N/A Storm Grate/Utility Hazard? N/A Ramp inside XWalk1? N/A Storm Grate/Utility Type N/A N/A Any Obstructions? **Obstruction Type** Surface Condition? (G/P) Yes N/A N/A Curb Slope (%)





Total Cost:



1600.00