

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 18095	Main Street: DRIFTER_DR	Cross Street: IDLEWILD_RD	Location: SW
ADA ID: E0B637899611	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 5	

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Landing.**  
**Remove & Replace Gutter.**

Surveyor Notes:

**LNDG SLOPE NEGATIVE**

PROW/ADA:

**R304.2.2-Perp, R304.3.2-Para,**  
**R304.5.3, R304.5.4**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	60.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	67.0	Yes	Grade Break Slope (%)	0.5
Yes	Ramp Slope (%)	0.1	Yes	Grade Break XSlope (%)	1.9
Yes	Ramp XSlope (%)	1.2			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Yes	Landing Length (in)	78.5	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	67.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	6.5	Yes	DWS Length (in)	24.0
No	Landing X Slope (%)	2.1	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	26.0
N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	0.0
Yes	Gutter Ponding?	No	No	Gutter Slope (%)	5.1
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.8
N/A	Painted X Walk1?	No		Road Slope (%)	6.4
	X Walk 1 Direction	To SE		Road X Slope (%)	1.0
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	6.4	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	1.0	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	3.2

Total Cost: \$ 1250.00

