

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31219 Main Street: HEADQUARTERS_FARM_RD Cross Street: WESTBURY_GLEN_CT Location: NE

ADA ID: E0C888542553 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 17.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name WESTBURY GLEN CT
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 1850.00

Compliance Description Data Compliance Description Data Yes N/A Ramp Length (in) 68.0 Ramp Slope (%) 5.0 Yes Ramp XSlope (%) No Ramp Width (in) 33.0 0.0 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A DWS Provided? N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To W X Walk 2 Direction N/A N/A N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 2.6 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 2.2 X Walk 2 X Slope (%) N/A N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? N/A Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A

Yes

Surface Condition? (G/P)

Good





